

Samples Shipping Instructions

What? Where to? How Long?



50-100 samples of the same type, for a reliable test result



If you have multiple parts to test, **select the most representative ones** (e.g., the smallest and the largest)



Make sure to include your **project's reference**, a **low unit value** (e.g. production costs) and a **detailed description of the components** ("free samples" doesn't suffice!)



ARS s.r.l.
Via Aretina Nord, 157
52041 Civitella in Val di Chiana (AR) - Italy



ARS Automation, Inc.
SUITE G - 5031 West W.T. Harris Blvd.,
Charlotte, NC 28269



1-2 weeks, depending on the type of test

What is the test process and what does it cover?

All test are free of charge and carried out in our fully equipped Lab.

We test all samples on FlexiBowl®, paired with our vision system FlexiVision and one of the available robots.

You will receive a video of the test, a report on vision detection and FlexiBowl® parameters.

Samples will be stored for 1 year and then will be recycled.

You can request the testing material to be returned at your expense.

Are you shipping from a non-EU country?


Make sure to ship in Incoterms DDP.

Please, share a copy of your shipping invoice for pre-acceptance and confirmation.

If any customs clearance costs occur for ARS, the parcel will be rejected.

Important!

- If you are shipping metal samples, please include a **certificate of the country of melt and origin**. Without such a certificate, a signed and stamped declaration from your company stating that the components don't originate from Russia would suffice.
- If you are shipping parts that contain chemicals, please provide a **certificate for the substance**.



Got more questions?

Feel free to contact us at sales@arsautomation.com